UNIVERSITY OF ILLINOIS AT URBANA-CHAMPAIGN

Facilities & Services

Transportation Demand Management Physical Plant Service Building 1501 South Oak Street Champaign, IL 61820



November 24, 2009 Student Sustainability Committee

RE: Bike Parking Grant

Through the generous support of the Student Sustainability Committee in 2008-2009, Facilities & Services is pleased to report the installation of three new or upgraded bike parking locations on campus this fall. Thank you very much for funding these much needed improvements to bicycle infrastructure!

We would like to work with the Student Sustainability Committee this year to prioritize and fund a number of additional bike parking locations. While we are still working toward a comprehensive solution to bicycle parking on campus, there are a dozen specific locations which have been brought forward by members of the campus community. I have reviewed these locations and rated each as high, medium, or low priority. The list is appended to this letter for your review and consideration.

A very rough estimate for each location was estimated based on the basic need at each site. A new bike parking area, on new concrete was estimated as approximately \$10,000. Retrofitting an existing dilapidated bike parking area was estimated as approximately \$4,500. Purchasing a new bike parking rack to be placed on existing concrete was estimated as approximately \$1,500.

Adequate bicycle parking is an essential piece of our campus efforts to shift people out of singleoccupancy vehicles. The design of campus racks has been agreed upon with the neighboring cities, and the design includes two dips of powder-coating to increase the life of the racks. By improving bicycle facilities throughout campus, we are encouraging students and staff to keep cars off campus. This project is highly visible to students, employees, and visitors, and each new location will proclaim the support from the SSC.

While, you are likely to receive many wonderful and exciting proposals this year, this is a simple request which will be used repeatedly by the students on campus for decades to come. In terms of student use and visibility, bike parking is at the top of the list.

Thank you for your consideration. I look forward to hearing from you.

Sincerely, Morgan B. Johnston

Morgan Johnston TDM Coordinator

Bicycle Parking Requests

Image: Section bit is statis and interpretating space. City of the statis and is the statis is space in a statis of the statis and is the statis is space in a statis of the statis and is the statis is space in a statis of the statis is space in a statis space in a statis of the statis space in a statis of t	1 Chan Use Some Nupl. 1 1.200 2 Bits Union - SEcorem Registing makes on the south exact conterment of the same base shares of the south exact bits parking with costs as a south exact bits parking base asouth e	#	location	current condition	impetus for request	contact name	priority	approx cost	Requested funding
Image: Solution: Set common processing rates and even processing rates an	Image: Second	1							
Image: Section of the sectio	Image: Section of the solution of the s		Lab	arranged for new racks, need to purchase			-		
2 Bird Linkin - SE carrent the limit Linkin and the did durit blac cask method in grapping regionalized tea outside the bird bird bird of grapping regionalized tea outside the parts and the parts and the parts and the parts plant ATR Bird Incode. high is solution of grapping regionalized tea outside plant ATR Bird Incode. high is solution of grapping regionalized tea outside plant ATR Bird Incode. high is solution of grapping regionalized tea outside plant ATR Bird Incode. high is solution of grapping regionalized tea outside plant ATR Bird Incode. high is solution of grapping regionalized tea outside plant ATR Bird Incode. high is solution of grapping regionalized tea outside solution of grapping regionalized tea outside plant ATR Bird Incode. high is solution of grapping regionalized tea outside tea outside tea outside tea outsis outside tea outside tea outside tea	2 Illei Ukon - SE comm the limit Ukon - SE comm the limit Ukon and the old data Num the direct process and the provide methods and the second base of process and the provider the Managar process and the process and the provider the Managar process and the proces			and install					
Image: International set of the distribution context in	Image: Section of the sectio								
Image: Solution of a set of the	Image: Solution of the section of the sectin of the section of the section of the section of the section of t	2	Illini Union - SE corner				high	\$ 10,000.00	\$ 8,000.0
Image: Source in the Stream of Stream o	Image: Problem is in the Winter under the Museur and the Winter under the Museur is in the Winter under the Winter Winter Under the Winter Under the Winter Under the Winter Under the Winter Winter Under the Winter Winter Under the Winter Winter Under the Winter Winter Winter Winter Under the Winter W			the Illini Union are the old donut-hole racks.					
Image: Second Part Part Part Part Part Part Part Part	Image: Instant and the second of a stating parting is of down of a rough parting, there is mark black down a stating parting is down of a rough parting, there is mark black down a parting is a down of a rough parting, there is mark black down a parting is a down of a rough parting, there is mark black down a parting is a down of a rough parting, there is no mark black down a parting is a down of a rough parting, there is mark black down a parting is a down of a rough parting, there is mark at black down a parting is a down of a rough parting, there is a constal down a rough down of a rough parting, there is a constal down a rough down of a rough parting, there is a constal down a rough down of a rough parting, there is a constal down a rough down of a rough parting, there is a constal down of a rough parting, there is a constal down of a rough parting down a rough down of a rough down of a rough parting down a rough down of a rough down o				,				
Image Image <th< td=""><td>Image: Image: Image:</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>	Image:								
3 Rammer Art Mussum Imited amount of existing parking is old down and reversals for the case, the release the set of the loce, the release the set of th	Knamer Ant Museum Initial amount of existing parking is old dom not enclose the states, etc. used domains glimota, state Number All and the state of the bits mark, which is before, these, etc. used domains glimota, state of the bits mark, which is before, these at least of the bits mark, which is before, the state of the bits mark, which is before, the state of the bits mark, which is before, the state of the bits mark, which is before, the state of the bits mark is by the grant back is carried state of the bits mark. Buds Allow, and the state of the bits mark, which is before, the state of the bits mark is by the grant back is the state of the bits mark. Buds Allow, and the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the grant back is the state of the bits mark is by the state of the bits mark is bits of the bits mark is by the state of the bits mark is bits of this bits of the bits mark is bits bits bits of the bits								
Index system Index system<	Index syle Index s				isodo min a la go loo a cal	211 000 0001			
Image: Second	Industry Industry <th< td=""><td>3</td><td>Krannert Art Museum</td><td>limited amount of existing parking is old donut</td><td>not enough parking, there are many bikes</td><td>David Akins,</td><td>high</td><td>\$ 14,500.00</td><td>\$ 11,600.0</td></th<>	3	Krannert Art Museum	limited amount of existing parking is old donut	not enough parking, there are many bikes	David Akins,	high	\$ 14,500.00	\$ 11,600.0
Image of the work and a contrain south instance Image base base and instance if the image base is also in part base base and instance if the image base is also in part base base is also in part them. The image base is also in part them base is the image base is also in part them. The image base is also in part them. The image base is also in part them base is the image base is also in part them. The image base is also in part them base is the image base is also in part them. The image base is also in the image base is also interest in the image base is also interest is also interest in the image base is also in	Image: Source instance of the bilar hand, which is source and the source instance of the bilar hand, which is source instance of the bilar hand, which is source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source instance of the bilar hand, which is the source is the bilar hand. Which hand hand, which is the source is the bilar hand, which is the source is the bilar hand. Which hand, which is the source is the bilar hand. Which hand, which is the source is the bilar hand. Which hand hand, which hand hand hand, which hand hand. Which hand hand, which hand hand, which h			hole style	chained to fences, trees, etc need	akins@illinois.edu	-		
4 Nullic Annex, 609 W. The general state of the bike rack, which is pole bad and state of the bike rack, which is pole bad and state of the bike rack, which is pole bad and state of the bike rack. Which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack, which is prove that B(Big 17) In state is the bike rack of provide is the bike rack of the prove that B(Big 17) In state is the bike rack of provide is the bike rack of the prove that B(Big 17) In state is the bike rack of provide is the bike rack of the prove that B(Big 17) In state is the bike rack of the prove that B(Big 17) In state is the bike rack of the prove that B(Big 17) In state is the bike rack of the prove that B(Big 17) In state is the bike rack of the prove that B(Big 17) In state is the bike rack of the prove that B(Big 17) In state is the bike rack of the prove that B(Big 17) In state is the bike rack of the prove that B(Big 17) In state is the prove that B(Big 17	4 Music Annex, 509 W. (http:pin B) The general state of the bike rank, which is use to and number safety and used/incress of rack Bob Stehl and others: http:// http:// 8 4.500.00 \$ 3.500 9 Interer Hall (Big 107) (more mark is bles percent gates and and number on greace). This has percent gates. The rack, more wave data the bit more cycle participant of the VW corner, and a large sate while bit corner, and a large sate while bit more cycle participant of the verce of the two corner, and a large sate while bitming. Reader is a 10,000.00 \$ 8.000 9 Turner Hall State 100 (100 (100 (100 (100 (100 (100 (100				update to SW corner bike parking, and				
Opegon St upter bad and nutled* Control type of the second of the secon	Oregon 3: Update bala and nutled" House				need new racks at central south entrance				
Opegon St upter bad and nutled* Control type of the second of the secon	Oregon 3: Update bala and nutled" House							^	<u> </u>
International state in the second state is the second state in the second state is the second state in the second state is	Internet Hall (Blog 107) Immediate as place to put them. The Section of the yout cannot be applied to put them. The Charles Smyth Charles Smyth Heet II 3.5,000,00 5 44.400 11/02.3. Gookum, U args, main mak is by the greenhouse and the put the NS concerns is surging each and there are 8 or more bias parking here. If many mere world if they yout. This is located with the standard with a strated marks that should be puved over and the motorycle parking here. If many mere world if they yout. This is located with the standard with the standard with the strated covered next to the greenhouses at the post here are to amply but down a put focuse. Heel II 3.10,000,00 5 8.000 6 Turner Hall/Studiading was fist half the read insets are built to bimming. medium 5 10,000,00 5 8.000 7 Mining here head in the world be parked here were 30 or more biase chained for long and these are to amply but down a put think is a part fisture were 30 or more biase chained for long and these are to amply but down a put for long. Towner Hall Studiadia II to 0,000,00 5 8.000 7 Mining here head in the part down an put think is a part fisture. There are no existing racks. medium 5 10,000,00 \$ 8.000 8 Gendeer Allowershift There were a solution and the part down and think is a part fisture. there there were 30 or more biase chained fisture the ante	4			safety and usefulness of rack	Bob Steini and others	nign	\$ 4,500.00	\$ 3,600.0
5 Turner Hall (Big 197, 197, 197, 197, 197, 197, 197, 197,	5 Timer Hall (Bill gifs): 1102 S. Goodvin, U. 102		Oregon St	quite bad and rusted			шец	\$ 20,500,00	¢ 24.400.0
112: S. Goodmi, U.J. large, main rack is by the greenhouses and is moveshie rack on the NV comer, and stage area the NV comer, and NV comer area the NV co	1102 S. Goodsin, U.) large, main rack is by the gramhouses and is moveable rack on the WU corner, another is a single rack and them control parating areas it has been due to the advectore and a large area with old style rack. The rack is a single rack and them control black bashing areas it has been due to the advectore and a large area with old style rack and them control black bashing areas it has been due to the advectore and a large area with old style rack and them control black bashing areas it has been due to the advectore and a large area with old style rack and them control black bashing areas it has been due to the advectore and a large area with old style rack and them control black bashing areas it has been due to the advectore and a large area with old style rack and them control black bashing areas it has been due to the advectore and a large area with old style rack and them control black are full to binnming. 6 Turner HallSouthade based for another blar rack in this area because there are to many blacks and the rooth large area to many blacks and there are no existing racks. Ware to save it to control black bashing base for throm ware 30 or more blacks chained the rooth size and blacks because there are to many blacks and the rooth size area to existing racks. Import to the grad base base base and the rooth size area to the process or more blacks chained the rooth size area to existing racks. Import to the size area	5	Turper Hall (Bldg 197	I'm not sure there's a place to put them. The	Currently, you can find a yery old style	Charlie Smyth			
a Congressed in the motor size single parking series at the NE concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and there is a concert is a single act and the concert is a single act and there is a concert is a single act and there is a concert is a single act and the concert is a concert is a single act and the concert is a concert is a single act and the concert is a concert is a single act and the concert is a concert is	image: set in the interaction in the motorycle parking area at the NE motorycle parking area at the NE motorycle parking parking there. It makes that should be paved over and remote which any the motorycle parking on significant invested during area at the NE is located with the standard invested during area at the NE is located with the standard invested during area at the NE is park discussed with the standard invested during area at the NE is park discussed with the standard invested during area at the NE is park discussed with the standard invested during area at the NE is park discussed with the standard invested during area at the NE is park discussed with the standard invested during area at the NE is park discussed with the standard invested during area at the standard the support of the standard the standard the standard the standard the standard the standard the support of the standard the support of the standard	5				Chanle Sinyth	mealum	\$ 10,000.00	φ 8,000.0
by the NE concer is a single rack and there, are 8 or more bikes patient ber. Im sum more would if they could. This is content and large pares with the standard invented U and control and the motorycle parking on a patient. content and large pares with the standard invented U and control and the motorycle parking on a patient. second State Sta	Image: Space of the space o		1102 0. 0000will, 0)						
aire 8 or more bites parking on agabat. Inclus that should be paved over and more would the yould. This is located with the motorsyce parking on agabat. Inclus that should be paved over and medicad with the should be paved over and provide on the building water is simply on the sidewalk to the outling water is simply on the sidewalk to the building water is simply on the sidewalk to the sole it to understand the sidewalk to the sole it to understand the sidewalk to the sole it to understand the sidewalk on the sole it to understand the sidewalk of the sole it to understand the sidewalk on the sole it to understand sidewalk on the sole it to understand the sidewalk on the sol	Image: Intermet Hall Participation of the control hists participation the motorcycle parking on apphalit. The motorcycle parking on parking. The motorcycle parking on parking on parking on parking. The motorcycle parking on parking parking on parking parking on parking parking parking parking parking parking								
Image: Second	Image: Instrume Full Southalds in the instrume for approximately space for version is a sphelit. The rack at the NV correct least to the greenhouses at Iuli to brimming. Pointe extra data are full to data and brief is pointed are full to brimming. Pointed are full to data and brief is pointed are full to data and brief is point and full to brief are full to data and brief is point and full to data and brief is point and full to brief are for any full to data and brief is point and full to data and brief is point and full to brief is point and full to brief are for any full to data and brief is point and full to brief is point and full to brief and full to data and brief is point and full to brief and and full to brief and and brief								
Image: Section of the motorcycle pairing on asphalt. covered not to the greenhouses at the southest end. The mack at the NV comer is stilling on the direction of th	Image: set in the motorsyste parking on asphale. The rack at the WY corner is stilling on the advocument to the ago dodu, the work on the drinks are full to brimming. when the building was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built fast was fast built. The validing was fast built. The validin								
automatic source is sating on the sidewalk to the dual, morth loading duck from when the building water source places on pours concrete. THere are several places on both the north/sets and NE to put down a pair though. southwest and, Inc. is good day, the two north and racks are full to brimming. southwest and, Inc. is places on the north/sets and NE to put down a pair though. southwest and, Inc. is places on the north sets are and places on pours concrete. THere are several places on though. southwest and, Inc. is places on the north sets are there are more places on the north side of Turner thicks it is just indicatous parking spaces (that is, there in there are should be and there is parking are constanting areas budies Program appet there were 30 or more blace channed Kinny Smith pager# 285-5994 at Seen# 285-5994 at Seen# 28	Image: Second								
Image: Second	Image: Second			service and a service service and a service servic					
side-walk to the outing was fits built. There's on place to put new racks here untess someone pour connects. There are several places on the north side of lumer here was been and the several place of understand the groups. Image: several place of understand the gr	islewalk to the olding work to lumit Process of breaks and the building work to lumit Process of breaks and the set of the Process of breaks and the break and the set of the Process of breaks and the break and the set of the Process of breaks and the break and the process of breaks and the process of breaks and the break and the break and the process of breaks and the break and the process of breaks and the break and the process and the process and the break and the process and the break and the process and the process and the break			The rack at the NW corner is sitting on the					
when the building was first buil. There's no places to put new racks there unless some pour soncetter. There are several places on both the northWest and NE to put down a part trough. when the building was first buil. There's no both the northWest and NE to put down a part trough. when the building was first buil. There's no both the northWest and NE to put down a part trough. when the building was first buil. There's no both the northWest and NE to put down a part trough. when the building was first buil. There's no both the northWest and NE to put down a part trough. when the building was first buil. There's no both the northWest and NE to put down a part trough. when the building was first buil. There's no to part the north was the part to mark there is no mark blace and the based of Madigan Hail access to the solution at F&S medium \$ 10,000.00 \$ 8,000.0 7 Christopher Hall at Nevada and Lincoln Studies Program There are no existing racks. When the building to regramment by the are no existing racks. No are to high programment by the are no existing racks. No are to high programment with the or are in the process of breaking no trough and the part or are in the process of breaking no mark rings and loces ones and so much runsting mark rings and loces ones and so much runsting mark rings and loces ones and so much runsting mark rings and loces of the was no mark rings and loces ones and so much runsting mark rings and loces ones and so much runsting mark rings and loces of the was no mark rings and loces of the w	when the building was first buil. There's no pours concrets. There are several places on both the north/vest and NE to put down a part though. when the both was part though. when the building was first buil. There is no both the north/vest and NE to put down a part though. when the building was first buil. There is no pours concrets. There are several places on though. when the building was first buil. There is no though. when the north/vest and NE to put down a part though and the north/vest and NE to put down and part though and though and though an								
Image: Provide and Line outbound in a constraint the north/West and NE to put down a part here were 30 or more bikes chanced (enry Smith pager) Image: Provide and Provi	pouts concrete. There are several places on both he nort/West and NE to put down a park though. pouts concrete. There are several places on both worth and the nort/West and NE to put down a park by under the park of								
both the northWest and NE to put down a pad hough. both the northWest and NE to put down a pad hough. both the northWest and NE to put down a pad hough. both the north west of the put down a pad provide the put down a pad of Madigan Hail both the north bide rack in this area of Madigan Hail both the north bide rack in this area of Madigan Hail both the north bide rack in this area of Madigan Hail both the north bide rack in this area of Madigan Hail both the north bide rack in this area of Madigan Hail both rest on the north side of Turner Down and the or the north side of Turner Down and the north side of Turner Down and the or the north side of Turner Down and the North side o	both the northWest and NE to put down a part You really have to see it to understand the layout. both the north west of the north side of turner because three are too many bless and he because three are too many bless and bless bless and bless bless bless access are bless bless and bless bless bless and bless bless bless access are bless bless and bless bless bless and bless bless bless access are bless bless and bless bless bless access are bless bless and bless bless bless access are bless bless and bless bless and bless bless access are bless bless and bless bless bless access are bless bless bless bless access are bless bless bless bless access are bless bless bless bless and three or four loops - honore than three or four loops - honore than three or four loops - honore (217) 333-5242 medium \$ 10,000.00 \$ 3,000 9 Education Building Research Center not encliph racks regar and loops of be breaken of three bless of parking park bless of breaking now. medium (217) 333-5242 medium (217) 33-5242								
Image: Section Participation of the section of the sectin of the section of the section of the section of the	Include								
Your really have to see it to understand the layout. Your really have to see it to understand the layout. Your really have to see it to understand the layout. Your really have to see it to understand the layout. Your really have to see it to understand the layout. Your really have to see it to understand the layout. Your really have to see it to understand the layout. Your really have to see it to understand the layout. Your really have to see it to understand the to trees on the north side of Turner to trees on the north side of Turner Parking spaces (hat is, there is in teven a parking space for Virginia Switcher in front of \$11 S. Skith Street. medium \$ 10,000.00 \$ 8,000.0 9 Education Building may rings could easily be broken off from the bar or are the process of breaking now. There is a concrete shab area in LOB 1-1 There is a	Variation Varia								
Image: second	Image:			though.					
Image: South Southside asked for another bike rack in this area of Madgan Hall for thisk is just ridiculous upset there were 30 or more bikes chained by the tes on the north side of Turner Hall/Southside of Madigan Hall for christopher Hall at norterity enough parking, or potential lilegan parking spaces (that is, there isn't even a parking spaces (that isn't even a parking spaces (that isn't even isn't even a test isn't even inter of 911 S. Stath Street. medium parking spaces (that isn't even parking spaces (that isn't even parking spaces (that isn't even inter of 911 S. Stath Street. medium parking spaces (that isn't even parking spaces (that isn't even parking spaces (that isn't even inter of 191 S. Stath Street. Medium Stath parking spaces (that isn't even parking spaces (that isn't even inter of 191 S. Stath Street. Medium Stath parking spaces (that isn't even parking spaces (that isn't even inter of 191 S. Stath Street. Medium Stath parking spaces (that isn't even parking spaces (that isn't even parking spaces or this parking area parked spaces or this parking area spaces (the bubic door access isn't head spaces or the space of the spa	Image:								
6 Turner Hall/Southside Asset for another bike rack in this area because there are too many bikes and he to trees on the north side of Turner 285-3904 at Steam medium 285-3904 at Steam medium 285-3904 at Steam 7 Christopher Hall at Neveda and Lincoh sit is just rickloulous not nearly enough parking, or potential lifegal nowhere to put bikes, and bikes blocking a nowhere to put bikes, and bikes blocking access Diane Martin medium \$10,000.00 \$ \$0,000.00 \$ \$0,000.00 \$ 8 Gender & Women's Studies Program There are no existing racks. W are looking for approximately space for Virginia Swisher on ornore than three or four loops - no more than three or four loops - Northwest Correr (No Trees - open grave) S1 0,000.00 \$ \$0,000.00 \$ \$0,000.00 \$ 9 Education Building It's a well-used rack and I see many missing many rings could easily be torken of from the bar or are in the process of breaking now. warted to suggest that the bike rack on low of \$1.5,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ 10 National Soybean Research Center not enough racks the auditorium is baing used as a closs coord mis year Carol Nellon low \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1,000.00 \$ \$1	6 Turner Halt/Southside Asked for another bike rack in this area because there are too many bikes and he difficultus upset there were 30 or more bikes chained for turner Distribution at FAS medium \$ 10,000.00 \$.000 7 Christopher Hall and Inkin is just ridiculous not nearly enough parking, or potential lilegal nowhere to put bikes, and bikes biocking and function at FAS Diane Marin medium \$ 10,000.00 \$.000 8 Gender & Women's Sudies Program There are no existing racks. W are looking for approximately space for Virginia Swisher structure of there or put now the or the or there or four loops - nor more than three or four loops - Northwest Corren (No Trees open grave) in front of 911 S. Sixth Street. medium \$ 10,000.00 \$.8,000 9 Education Building It's a well-used rack and I see many missing ring and loose ones and so much rust that many rings could easily be broken off from the bar or are in the process of breaking now. wated to suggest that the bike rack on classroom this year medium \$ 4,500.00 \$ 1,200 10 National Stybean Recearch Center not enough racks the auditorium is being used as a classroom this year Carol Nellson low \$ 10,000.00 \$.000 11 WiLL building Mecurently have a bkee parking arcos the cost of breaking now. the auditorium is being used as a classow of threaking now mechand several employees as ktor								
of Madigan Hall because there are too many bikes and he hit fixes in just indiculous to trees on the north side of Tumer Bit Schulards of Madigan Hall nowhere to put bikes, and bikes blocking acces 265-390.4 at Steam Distribution at 1545 Image: Steam Bit Schulards of Madigan Hall nowhere to put bikes, and bikes blocking acces Diane Marlin medium \$ 10.000.00 \$ 8.000.0 8 Gender & Women's Studies Program There are no existing racks. We are looking for approximately space for tor tore to run three or four loops - no more than three or four loops - no more than three or four loops - no more than three or four loops - nom ore than three or four loops - Non threes Comer (NM) Image: Studies Program The average three are no existing racks. Mean to submest Comer (NM) Helen Katz hnkatz Billinios.edu 217:333-2290 medium \$ 1.000.00 \$ 3.600.0 9 Education Building Research Center Int enough racks many rings could easily be broken off from many rings could easily be broken off from many rings could easily be broken off from many fings could easily be track on the sast side need stear or replacement Carol Neilson MEDIUM \$ 4.4500.00 \$ 1.200.0 10 National Scybean Research Center not enough racks compatibility have a bike parking area incated across Goodwin Avenue from Campability Hault. Bill to compatibility area size weatores to the bow in the rack in the weat area in Lot 8-17 three is a concrete sibe area in Lot 8-17 three is a concrete sibe area in Lot 8-17 three is a concrete sibe area in Lot 8-17 three is a conc	of Madigan Hall because there are too many bikes and he Hull/Southside of Madigan Hall Distribution at FSS 7 Christopher Hall at Nevada and Lincoh herder 50 use incorrectly) not nearly enough parking, or potential liegal nowhere to put bikes, and bikes blocking lence to use incorrectly. Diane Marlin medium \$ 10,000.00 \$ 8,000 8 Gender & Women's Studies Program There are no existing racks. We are looking for approximately space for no more than three or four loops - no more than three or replacement Melankatz bliniois.edu 217:333-5242 medium \$ 4,500.00 \$ 4,500.00 \$ 3,600 9 Education Building many rings could easily be broken off from the bar or are in the process of breaking now. the auditorium is being used as a classroom this year Carol Neilson medium \$ 10w \$ 1,000.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500			layout.					
of Madigan Hall because there are too many bikes and he hilt bicks it is just reliation to trees on the north side of Turner Hall Soudiage I Malling Hall nowhere to put bikes, and bikes blocking acces 265-390.4 at Steam E 7 Christopher Hall at Nevada and Lincoh nedre & Women's Studies Program not nearly enough parking, space (rule in force to use incorrecity) not nearly enough parking, space (rule in force to use incorrecity) S 10.000.00 \$ 8.000.0 8 Gende & Women's Studies Program There are no existing racks. We are looking for approximately space for Virginia Swisher on more than three or four loops - Northwest Corner (No Trees- open grave) Yells. Slich Street Phone (217) 333-2990 nedium \$ 10.000.00 \$ 8.000.0 9 Education Building Research Center It's a well-used rack and I see many missing many rings cuid easily be broken off from many rings cuid easily be broken off from many rings cuid easily be broken off from many rings cuid easily be broken off to many fings cuid easily be praking area located across Goodwin Avenue from Comparison Lince Research Center Inel enough racks Carol Nellon Iow \$ 1.000.00 \$ 8.000.0 11 WilL building Net currently have a bike parking area located across Goodwin Avenue from Comparison Lince Research Center Ineed caro, in concerte sila area in Lot B-17 Prote 12 / 224-2625 Iow \$ 1.000.00 \$ </td <td>of Madigan Hall because there are too many bikes and he Hull/Southside of Madigan Hall Distribution at FSS 7 Christopher Hall at Nevada and Lincoh herder 50 use incorrectly) not nearly enough parking, or potential liegal nowhere to put bikes, and bikes blocking lence to use incorrectly. Diane Marlin medium \$ 10,000.00 \$ 8,000 8 Gender & Women's Studies Program There are no existing racks. We are looking for approximately space for no more than three or four loops - no more than three or replacement Melankatz bliniois.edu 217:333-5242 medium \$ 4,500.00 \$ 4,500.00 \$ 3,600 9 Education Building many rings could easily be broken off from the bar or are in the process of breaking now. the auditorium is being used as a classroom this year Carol Neilson medium \$ 10w \$ 1,000.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500</td> <td>6</td> <td>Turper Hall/Southside</td> <td>asked for another hike rack in this area</td> <td>upset there were 30 or more bikes chained</td> <td>Kenny Smith pager#</td> <td>medium</td> <td>\$ 10,000,00</td> <td>\$ 000 8</td>	of Madigan Hall because there are too many bikes and he Hull/Southside of Madigan Hall Distribution at FSS 7 Christopher Hall at Nevada and Lincoh herder 50 use incorrectly) not nearly enough parking, or potential liegal nowhere to put bikes, and bikes blocking lence to use incorrectly. Diane Marlin medium \$ 10,000.00 \$ 8,000 8 Gender & Women's Studies Program There are no existing racks. We are looking for approximately space for no more than three or four loops - no more than three or replacement Melankatz bliniois.edu 217:333-5242 medium \$ 4,500.00 \$ 4,500.00 \$ 3,600 9 Education Building many rings could easily be broken off from the bar or are in the process of breaking now. the auditorium is being used as a classroom this year Carol Neilson medium \$ 10w \$ 1,000.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500.00 \$ 1,500	6	Turper Hall/Southside	asked for another hike rack in this area	upset there were 30 or more bikes chained	Kenny Smith pager#	medium	\$ 10,000,00	\$ 000 8
Image: Structure in thinks it is just ridiculous in the subscription of marks is just ridiculous in the subscription of the subscriptic subscription of the subscription of the subscriptio	Image: constraint of the set of the	0					mealum	\$ 10,000.00	φ 8,000.0
7 Christopher Hall at Nevada and Lincoln Hevda and Lincoln Parking spaces (Mat is, there isn't even a fence to use incorrectly) 8 10.000.00 \$ 8.000.0 8 Gender & Women's Studies Program There are no existing racks. We are tooking for approximately space for Virginia Swisher no more than three or four loops - no more than three or four loops - in front of 911 S. Sixth Street. medium \$ 10.000.00 \$ 8.000.0 9 Education Building Research Center It's a well-used rack and I see many missing ings and loose ones and so much rust that many rings could easily be broken off from the bar or are in the process of breaking now. wanted to suggest that the bite rack on loads repair or replacement Helen Katz hinkatz @illinois.edu 217-333-5242 medium \$ 4,500.00 \$ 3,600.0 10 National Stybean Research Center not enough racks the auditorium is being used as a classroom this year hocated acrass Goodwink Avenue from welcome to park their bikes there. the auditorium is being used as a classroom this year hocated acrass Goodwink Avenue from welcome to park their bikes there. Net Multiculate how welcome as the rack. Net Multiculate how welcome access to the toure, resets there were cards. We issued avera all employ has a classroom this year next to the VILL tour frame where we cards. We issued avera all were for were were to access to the tourier tous where were access to the tourier. Net Madigan Email nellm@illinois.edu veetomer@uuc.edu Net Madigan Email nellm@illin	7 Christopher Hall at Neveral and Lincoln Warking spaces (that is, there isn't even a lance to use incorrectly) access nowhere to put blkes, and blkes blocking access Diane Marin medium \$ 10,000.00 \$ 8,000 8 Gender & Women's Studies Program There are no existing racks. We are looking for approximately space for Virginia Swisher no more than three or four loops - nore than three or four loops - Norm well 1S, Sixth Street Normayain, Lie Stath Street Normay ings could easily be broken off from the bar or are in the process of breaking now. medium to suggest that the bike rack on the bar or are in the process of breaking now. Medium S 44,500.00 \$ 45,000.00 \$ 3,600 10 National Soybean Research Center Inter are in the process of breaking now. Meautifolium is being used as a classroom this year inter a classroom this year inter is a concrete slab area in Lot B-17 Research Center Imedium N \$ 10,000.00 \$ 1,000.00 \$ 8,000 11 WILL building We currently have a bike parking area located across Goodwin Arenue from cars in their bikes there. Imer is a concrete slab area in Lot B-17 Research Center Ilow N \$ 10,000.00 \$ 10,000.00 \$ 8,000 11 WILL building We currently have a bike parking area in the the bikes there. Inter is a concrete slab area in Lot B-17 Research Center Ilow N \$ 10,000.00		or wadigari riali	-					
Nevada and Lincoln parking spaces (that is, there isn't even a more than these or four loops - four loops - Northwest Corner (No Trees- open gravel) medium stock stock <td>Nevada and Lincoln parking spaces (that is, there isn't even a mean back to work there to use incorrectly) access access access 8 Gender & Women's Studies Program There are no existing racks. There are no existing racks. We are looking for approximately space for Virginia Swisher of 115. Skith Street. medium \$ 10,000.00 \$ 8,000 9 Education Building It's a well-used rack and I see many missing ings and loose ones and so much rust that many rings could easily be broken off from ings and loose ones of breaking now. Meatoral Soybean medium \$ 4,500.00 \$ 3,600 10 National Soybean not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 1,500.00 \$ 1,200 11 WILL building We currently have a bike parking area in the parking area in classroom this year There is a concrete slab area in to H=71 Elizabeth A. Weathers low low \$ 10,000.00 \$ 8,000 11 WILL building We currently have a bike parking area in the the building with heir prox cards. We subter form than parking spaces or with the building with heir prox cards. We subter form than parking spaces or with the building with heir prox cards. We subter for the to WELL building located across Goodwin Avenue from Campbell Hall. It is located on the east link to have a bike rack. It wouldn't ave have acces to the building with heir prox cards. We issued very fe</td> <td>7</td> <td>Christopher Hall at</td> <td></td> <td></td> <td></td> <td>medium</td> <td>\$ 10,000,00</td> <td>\$ 8,000 (</td>	Nevada and Lincoln parking spaces (that is, there isn't even a mean back to work there to use incorrectly) access access access 8 Gender & Women's Studies Program There are no existing racks. There are no existing racks. We are looking for approximately space for Virginia Swisher of 115. Skith Street. medium \$ 10,000.00 \$ 8,000 9 Education Building It's a well-used rack and I see many missing ings and loose ones and so much rust that many rings could easily be broken off from ings and loose ones of breaking now. Meatoral Soybean medium \$ 4,500.00 \$ 3,600 10 National Soybean not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 1,500.00 \$ 1,200 11 WILL building We currently have a bike parking area in the parking area in classroom this year There is a concrete slab area in to H=71 Elizabeth A. Weathers low low \$ 10,000.00 \$ 8,000 11 WILL building We currently have a bike parking area in the the building with heir prox cards. We subter form than parking spaces or with the building with heir prox cards. We subter form than parking spaces or with the building with heir prox cards. We subter for the to WELL building located across Goodwin Avenue from Campbell Hall. It is located on the east link to have a bike rack. It wouldn't ave have acces to the building with heir prox cards. We issued very fe	7	Christopher Hall at				medium	\$ 10,000,00	\$ 8,000 (
Image: Second state of the second s	Image: constraint of the second se	•					moulain	φ,	φ 0,000.
8 Gender & Women's Studies Program There are no existing racks. We are looking for approximately space for Virginia Swisher nome than three or four loops - 9 medium \$ 10,000.00 \$ 8,000.0 9 Education Building many ings and loose ones and so much rust that many ings could easily be troken of from rings and loose ones and so much rust that many ings could easily be broken off from races of breaking now. wated to suggest that the bike rack on rings and loose ones and so much rust that many ings could easily be broken off from research Center Medium \$ 4,500.00 \$ 3,600.0 10 National Soybean Research Center not enough racks the auditorium is being used as classroom this year Carol Nelson MeDIUM \$ 4,500.00 \$ 1,000.00 \$ 1,000.00 \$ 1,000.00 \$ 3,600.0 11 WILL building not enough racks the auditorium is being used as classroom this year Carol Nelson Image S 10,000.00 \$ 1,000.00 \$ 1,000.00 \$ 1,000.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the welcome to park their bikes there. Interes is a concrete slab are in Lot B-17 in getting complaints about the racks areak closer to the back door where they rack do ser to the back door where they rack do ser to the back door viter or rack do ser to the back door viter or rack do ser to the back door viter or rack do ser to the back door intor on to dor, so back or side door access is preferable. <td>8 Cender & Women's Studies Program There are no existing facks. We are looking for approximately space for Virginia Swisher nome than three or four loops - 911.S. Sixth Street. medium \$ 10,000.00 \$ 8,000 9 Education Building many fings could easily be tooken of ings and loose ones and so much rust that many fings could easily be tooken of from the bar or are in the process of breaking area (cases of the back door where the vould like to have a bike parking area (cases to the tower. (cards Nellson) Immedium (cases of breaking area (cases of the back door where the vould like to have a bike to ray area (cases to the tower. (cards Nellson) Immedium (cases to the back door where the vould like to have a bike to ray (cards. We issued very the ways to the vould like to have a back or area (cards. We issued very the ways to the voer. One profees ark for a rack closer to the back door access is (cards. We issued very the houlding with their prox (cards. We issued very the houlding with their prox (cards. We issued very the ways to hour cards. We issued very the ways to hour (cards. We issued very the ways to hour cards. We issued very the ways to hour (cards. We issued very the ways to hour some concrete (cards. We issued very the ways to hour some concrete (cards. We issued very the ways to hour some concrete (cards. We issued very the way to pury aperson (cards. We issued a</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	8 Cender & Women's Studies Program There are no existing facks. We are looking for approximately space for Virginia Swisher nome than three or four loops - 911.S. Sixth Street. medium \$ 10,000.00 \$ 8,000 9 Education Building many fings could easily be tooken of ings and loose ones and so much rust that many fings could easily be tooken of from the bar or are in the process of breaking area (cases of the back door where the vould like to have a bike parking area (cases to the tower. (cards Nellson) Immedium (cases of breaking area (cases of the back door where the vould like to have a bike to ray area (cases to the tower. (cards Nellson) Immedium (cases to the back door where the vould like to have a bike to ray (cards. We issued very the ways to the vould like to have a back or area (cards. We issued very the ways to the voer. One profees ark for a rack closer to the back door access is (cards. We issued very the houlding with their prox (cards. We issued very the houlding with their prox (cards. We issued very the ways to hour cards. We issued very the ways to hour (cards. We issued very the ways to hour cards. We issued very the ways to hour (cards. We issued very the ways to hour some concrete (cards. We issued very the ways to hour some concrete (cards. We issued very the ways to hour some concrete (cards. We issued very the way to pury aperson (cards. We issued a								
Image: Solution of the set of the s	Image: Second Processing Second Processing Second Processing Second Processing Second Processing Processing Second Processing Procesprocessing Processing Processing Processing Pr	8	Gender & Women's	There are no existing racks.	We are looking for approximately space for	Virginia Swisher	medium	\$ 10,000.00	\$ 8,000.0
9 Education Building It's a well-used rack and I see many missing many fings could easily be troken off from many fings could easily be troken off from the bar or are in the process of breaking now. wanted to suggest that the bike rack on prebody by the Education Building bady he bar of are in the process of breaking now. Helen Katz http://many.fings.edu medium \$ 4,500.00 \$ 3,600.0 10 National Soybean not enough racks the auditorium is being used as a classroom this year new to the year of are in the process of breaking now. the auditorium is being used as a classroom this year new to the WLL tower fines where we would like to have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are interfere with any parking spaces or with welcome to park their bikes there. Inter is a concrete slab area in Lot B-17 new: 217/244-2625 evant welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000.0 12 ILIR old style rack, and there is parking across the street. Index street were received were welcome to park their bikes there. Nell Madigan Email nellm@illin@ill	Image: Sixth Street. Phone (217) 333-2990 Image: Sixth Street. Phone (217) 333-5242 Image: Sixth Street. Phone (217) 333-5242 Image: Sixth Street. Image: Sixth Street. Image: Sixth Street. Phone (217) 333-5242 Image: Sixth Street. Image: Sixth Street. <td< td=""><td></td><td>Studies Program</td><td>-</td><td>no more than three or four loops -</td><td>911 S. Sixth Street</td><td></td><td></td><td></td></td<>		Studies Program	-	no more than three or four loops -	911 S. Sixth Street			
9 Education Building It's a well-used rack and I see many missing may may rings could easily be broken off from the bar or are in the process of breaking now. wanted to suggest that the bike rack on needs repair or replacement Helen Katz many rings could easily be broken off from the bar or are in the process of breaking now. medium set (217-333-5242) medium set (217-333-5242) medium set (217-333-5242) set (217-333-5242) 10 National Soybean Research Center not enough racks the auditorium is being used as a load code aross Goodwin Avenue from to the VILL tower frace where we would like to have a bike rack. In wouldn't like to have a bike rack in the is a concrete slab area in Lot B-17 next to the VILL tower frace where we would like to have a bike rack. In wouldn't like vanue would like to have a bike rack. In wouldn't like on the east site of Parking Deck B-4. Campbell Hall folks are interfere with any parking spaces or with area cases to the bourd. In the vanue of the tower. Elizabeth A. Weathers 300 N Goodwin Avenue from the vanue access to the bourd on scenes is preferable. Iow \$ 10,000.00 \$ 8,000.0 12 ILIR old style rack, and there is parking across the first or building, but we have to buy an expensive rack for a new rolliding. Univ on the or so the door access is preferable. Nell Madigan Email nellime Willing with their proces on the own cellime will ble falls over one profiles Proce and the work on your wants us to buy an expensive rack for a new rollime. Nell Madigan Email nellime Will tower were they have access to the building with their proces on the own cellime on the were they have access to the building with their proces	9 Education Building It's a well-used rack and I see many missing may ings could easily be broken off from the bar or are in the process of breaking now. wanted to suggest that the bike rack on Peebody by the Education Building badry needs repair or replacement Helen Katz minkatz@illinois.edu 217-333-5242 medium \$ 4,500.00 \$ 3,600 10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Nelison low \$ 1,500.00 \$ 1,200 11 WILL building We currently have a bike parking area located across Goodwin Avenue from evolution to the bay abike rack. It wouldn't may have abike rack. It wouldn't may have abike rack. It wouldn't meet on the east door where they have access to the back door where were then the first or so back or side door access is preferable. Nell Madigan Email email email mellim@illinois.edu I ow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the street being the 'potato chip' type that damages wheelis if the bike fails over or professor was us to buy an expensive rack. Over were writeling Office Prone control woulding, but we have to buy an expensive rack. to were writ litte Nell Madigan Email email				Northwest Corner (No Trees- open gravel)	Champaign, IL 61820			
10 National Soybean Research Center not enough racks Peabody by the Education Building badly needs repair or replacement hnkatz @illinois.edu 217-333-5242 hnkatz @illinois.edu 217-333-5242 10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 1,500.00 \$ 0,000.00 11 WiLL building We currently have a bike parking area located across Goodwin Avenue from campbel Hall. It is tocated on the east ide welcome to park their bikes there. There is a concrete slab area in Lot B-17 next to the WILL tower fence where we welcome to park their bikes there. National Soybean rack Closer to the back door where they have access to the burer. Elizabeth A. Weathers 300 N Goodwin Avenue Iow \$ 10,000.00 \$ 8,000.0 12 ILIR old style rack, and there is parking across the street Image tigting complaints about the racks across the the back door where they have access to the building with their prox cards. We issued very few keys to the front door, so back or side door access is preferable. Nell Madigan Email nellm@illinois.edu Neild Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the treet Image the propriation about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new rack, but we'd have to pour some concrete to set it on. Nell Madigan	10 National Soybean Research Center not enough racks The auditorium is being used as a classroom this year Carol Neilson Iow \$ 44,500.00 \$ 35,600 10 National Soybean Research Center not enough racks There is a concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the val to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the back door where they have access to the tower. Iow as it is concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 12 ILIR old style rack, and there is parking across the street In exit the welch cover welch have access to the building with their protato chip ⁵ tope that damages wheels if the bike falls over. One professor wants us to buy a network arack, for our building, but we have to put some concrete to set it on. Nell Madigan Email nell @illinois.edu Nell Iow \$ 4,500.00 \$ 3,600				in front of 911 S. Sixth Street.	Phone (217) 333-2990			
10 National Soybean Research Center not enough racks Peabody by the Education Building badly needs repair or replacement hnkatz @illinois.edu 217-333-5242 hnkatz @illinois.edu 217-333-5242 10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 1,500.00 \$ 0,000.00 11 WILL building We currently have a bike parking area located across Goodwin Avenue from campbell Hall. It is located on the east ide of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 next to the WILL tower fence where we cambell Hall. It is located on the east ide welcome to park their bikes there. Inve to the wall tower face. It wouldn't interfere with any parking spaces or with access to the building with their prox cards. We issued very few keys to the front door, so Dack or side door access is preferable. Iow \$ 4,500.00 \$ 4,500.00 12 ILIR old style rack, and there is parking across the street Im getting complaints about the racks across the street being the "pototo chip" hype that damages wheels if the bike falls over. One professor wants us to buy a nexpensite ach, but we have very little) Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking we have even street Im getting complaints about the racks across the street being the "pototo chip" hype that damages wheels if the bike falls over. One professor wants us t	10 National Soybean Research Center not enough racks The auditorium is being used as a classroom this year Carol Neilson Iow \$ 44,500.00 \$ 35,600 10 National Soybean Research Center not enough racks There is a concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the val to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the back door where they have access to the tower. Iow as it is concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 12 ILIR old style rack, and there is parking across the street In exit the welch cover welch have access to the building with their protato chip ⁵ tope that damages wheels if the bike falls over. One professor wants us to buy a network arack, for our building, but we have to put some concrete to set it on. Nell Madigan Email nell @illinois.edu Nell Iow \$ 4,500.00 \$ 3,600								
10 National Soybean Research Center not enough racks Peabody by the Education Building badly needs repair or replacement hnkatz @illinois.edu 217-333-5242 hnkatz @illinois.edu 217-333-5242 10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 1,500.00 \$ 0,000.00 11 WILL building We currently have a bike parking area located across Goodwin Avenue from campbell Hall. It is located on the east ide of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 next to the WILL tower fence where we cambell Hall. It is located on the east ide welcome to park their bikes there. Inve to the wall tower face. It wouldn't interfere with any parking spaces or with access to the building with their prox cards. We issued very few keys to the front door, so Dack or side door access is preferable. Iow \$ 4,500.00 \$ 4,500.00 12 ILIR old style rack, and there is parking across the street Im getting complaints about the racks across the street being the "pototo chip" hype that damages wheels if the bike falls over. One professor wants us to buy a nexpensite ach, but we have very little) Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking we have even street Im getting complaints about the racks across the street being the "pototo chip" hype that damages wheels if the bike falls over. One professor wants us t	10 National Soybean Research Center not enough racks The auditorium is being used as a classroom this year Carol Neilson Iow \$ 44,500.00 \$ 35,600 10 National Soybean Research Center not enough racks There is a concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the val to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the back door where they have access to the tower. Iow as it is concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 12 ILIR old style rack, and there is parking across the street In exit the welch cover welch have access to the building with their protato chip ⁵ tope that damages wheels if the bike falls over. One professor wants us to buy a network arack, for our building, but we have to put some concrete to set it on. Nell Madigan Email nell @illinois.edu Nell Iow \$ 4,500.00 \$ 3,600								
10 National Soybean Research Center not enough racks Peabody by the Education Building badly needs repair or replacement hnkatz @illinois.edu 217-333-5242 hnkatz @illinois.edu 217-333-5242 10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 1,500.00 \$ 0,000.00 11 WILL building We currently have a bike parking area located across Goodwin Avenue from campbell Hall. It is located on the east ide of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 next to the WILL tower fence where we cambell Hall. It is located on the east ide welcome to park their bikes there. Inve to the wall tower face. It wouldn't interfere with any parking spaces or with access to the building with their prox cards. We issued very few keys to the front door, so Dack or side door access is preferable. Iow \$ 4,500.00 \$ 4,500.00 12 ILIR old style rack, and there is parking across the street Im getting complaints about the racks across the street being the "pototo chip" hype that damages wheels if the bike falls over. One professor wants us to buy a nexpensite ach, but we have very little) Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking we have even street Im getting complaints about the racks across the street being the "pototo chip" hype that damages wheels if the bike falls over. One professor wants us t	10 National Soybean Research Center not enough racks The auditorium is being used as a classroom this year Carol Neilson Iow \$ 44,500.00 \$ 35,600 10 National Soybean Research Center not enough racks There is a concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the val to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 in the back door where they have access to the tower. Iow as it is concrete slab area in Lot B-17 in exit to the WILL tower fence where we welcome to park their bikes there. Iow \$ 10,000.00 \$ 8,000 12 ILIR old style rack, and there is parking across the street In exit the welch cover welch have access to the building with their protato chip ⁵ tope that damages wheels if the bike falls over. One professor wants us to buy a network arack, for our building, but we have to put some concrete to set it on. Nell Madigan Email nell @illinois.edu Nell Iow \$ 4,500.00 \$ 3,600	•	Education Dudidic a			I lalan Kata		¢ 4,500,00	¢ 0.000/
10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 44,500.00 \$ 35,600.0 11 WILL building We currently have a bike parking area located across Godwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 inter is a concrete slab area in Lot B-17 into to have a bike rack. It wouldn't interfere with any parking spaces or with access to the tower. Iow \$ 10,000.00 \$ 8,000.0 12 LIR old style rack, and there is parking across the street Im getting complaints about the racks arck for our building, but we have very little outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm @illinois.edu Nell Iow \$ 4,500.00 \$ 3,600.0	many rings could easily be broken off from the bar or are in the process of breaking now. needs repair or replacement 217-333-5242 218-333-5242 10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson low \$ 44,500.00 \$ 0.5,600 11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete siab area in Lot B-17 exercise as to the tower. Carol Neilson Iow \$ 10,000.00 \$ 8,000 12 ILIR old style rack, and there is parking across the street old style rack, and there is parking across the street I'm getting complaints about the racks across to street othe back of or where the preferable. Nell Madigan Email nellm @illinois.edu Iow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks ack for our building, but we have very little over. One professor wants us to buy an exerpsive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm @illinois.edu Iow \$ 4,500.00 \$ 3,600	9	Education Building	, , ,			meaium	\$ 4,500.00	\$ 3,600.0
Interview Medium Medium <td>Image: National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson Iow \$ 44,500.00 \$ 0.95,600 10 National Soybean Research Center Me currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 here is a concrete slab area in Lot B-17 ext to the WILL tower fence where we would like to have a bike rack. It wouldn't access to the tower. Elizabeth A. Weathers 300 N Goodwin Avenue Iow \$ 10,000.00 \$ 8,000 12 LLR old style rack, and there is parking across the street we issued very few keys to the front door, so back or side door access is preferable. Nell Madigan Email nellm@illinois.edu Netid Iow \$ 4,500.00 \$ 3,600 12 LLR old style rack, and there is parking across the street street mg eting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls Nell Madigan Email nellm@illinois.edu Netid Iow \$ 4,500.00 \$ 3,600</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Image: National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson Iow \$ 44,500.00 \$ 0.95,600 10 National Soybean Research Center Me currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 here is a concrete slab area in Lot B-17 ext to the WILL tower fence where we would like to have a bike rack. It wouldn't access to the tower. Elizabeth A. Weathers 300 N Goodwin Avenue Iow \$ 10,000.00 \$ 8,000 12 LLR old style rack, and there is parking across the street we issued very few keys to the front door, so back or side door access is preferable. Nell Madigan Email nellm@illinois.edu Netid Iow \$ 4,500.00 \$ 3,600 12 LLR old style rack, and there is parking across the street street mg eting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls Nell Madigan Email nellm@illinois.edu Netid Iow \$ 4,500.00 \$ 3,600								
Image: Note of the second s	Image: Notional Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson Iow \$ 44,500.00 \$ 35,600 11 WILL building We currently have a bike parking area incate of a cross Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 ince where we would like to have a bike rack. It wouldn't ket to have a bike rack. It wouldn't access to the WILL tower fence where the have access to the tower. I have had several employees ask for a rack closer to the back door where the have access to the building with their prox cards. We issued very few keys to the fort door, so back or side door access is preferable. Nell Madigan Email nellim@illinois.edu Netid Iow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellim@illinois.edu Iow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls Nell Madigan Email nellim@illinois.edu Iow \$ 4,500.00 \$ 3,600 \$ 4,500.00					211-000-0242			
10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson Iow \$ 1,500.00 \$ 1,200.0 11 WILL building We currently have a bike parking area located across Goodwin Avenue from campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 next to the WILL tower fence where we would like to have a bike rack. It wouldn't interfere with any parking spaces or with access to the tower. Sub Roodwin Avenue Iow \$ 10,000.00 \$ 8,000.0 12 ILIR old style rack, and there is parking across the street old style rack, and there is parking across the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu Nelid Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu Nelid Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks over. One professor wants us to buy a ne	10 National Soybean Research Center not enough racks the auditorium is being used as a classroom this year Carol Neilson Iow \$ 1,500.00 \$ 1,200 11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are welcome to park their bikes there. There is a concrete slab area in Lot B-17 next to the WILL tower fence where we would like to have a bike rack. It wouldn't interfere with any parking spaces or with access to the tower. Iow \$ 10,000.00 \$ 8,000 12 ILIR old style rack, and there is parking accoss the street old style rack, and there is parking accoss the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels life to bik falls over. One professor wants us to buy a new rack for our building, but we have very little outdoor space and I'm confident that not. Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600								
Research Center classroom this year clascccss to the building clob year	Research Center classroom this year clascess to the weithing year classroom this			•	• 		MEDIUM		
11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are would like to have a bike rack. It wouldn't would like to have a bike rack. It wouldn't Avenue Wrban IL 61801 Elizabeth A. Weathers 300 N Goodwin Avenue from Campbell Hall folks are would like to have a bike rack. It wouldn't Avenue Wrban IL 61801 Iow \$ 10,000.00 \$ 8,000.0 12 ILIR old style rack, and there is parking across the street I'm geting complaints about the racks across to bike bike for a rack closer to the bike for the vace or your few keys to the front door, so back or side door access is preferable. Nell Madigan Email Netid Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the to pour some concrete to park to the vace or your building, but we have very little Office Phone only would we have to buy an expensive rack, but we'd have to buy an expensive rack, but we'd have to buy an expensive rack, but we'd have to pour some concrete to set it on. Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the to pour some concrete to set it on. I'm geting complaints about the racks acces to buy an expensive rack, but we'd have to buy an expensive rack, but we'd have to pour some concrete to set it on. Iow \$ 4,500.00 \$ 4,500.00 \$ 5,600.00 12 ILIR old style rack, and	11 WILL building We currently have a bike parking area located across Goodwin Avenue from Campbell Hall. It is located on the east side of Parking Deck B-4. Campbell Hall folks are would like to have a bike rack. It wouldn't welcome to park their bikes there. There is a concrete slab area in Lot B-17 wouldn't low are to the WILL tower fence where we would like to have a bike rack. It wouldn't wouldn't would with their pox cards. We issued east side of Parking Deck B-4. Campbell Hall folks are interfere with any parking spaces or with welcome to park their bikes there. I have had several employees ask for a rack closer to the back door where they have access to the building with their prox cards. We issued very few keys to the front door, so back or side door access is preferable. Nell Madigan Email nellm@illinois.edu I ow \$ 4,500.00 \$ 4,500.00 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm nellm@illinois.edu Nell Madigan Email nellm@illinois.edu I ow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the is parking across the tree to being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu I ow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the is parking across the is treet being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm <td>10</td> <td></td> <td>not enough racks</td> <td></td> <td>Carol Neilson</td> <td>low</td> <td>\$ 1,500.00</td> <td>\$ 1,200.0</td>	10		not enough racks		Carol Neilson	low	\$ 1,500.00	\$ 1,200.0
12 ILIR old style rack, and there is parking across the street next to the WILL tower fence where we would like to have a bike rack. It wouldnik interfere with any parking spaces or with access to the tower. 300 N Goodwin Avenue 300 N Goodwin Avenue 12 ILIR old style rack, and there is parking across the street image across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm rack for our building, but we have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600.0	12 ILIR old style rack, and there is parking across the street in ext to the WILL tower fence where we would like to have a bike rack. It wouldn't interfere with any parking spaces or with access to the tower. 300 N Goodwin Avenue 300 N Goodwin Avenue 12 ILIR old style rack, and there is parking across the street interfere withing complaints about the racks across to street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new rack for our building, but we have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm@illinois.edu Netid low \$ 4,500.00 \$ 3,600							A 10	^
12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls our our building, but we have to buy an expensive rack, but we'd have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email of Magina IL 61801 Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the low or under the building with their proxing the to building with their proxing the to building with their proxing the total door access is preferable. Nell Madigan Email of Net to building with their proxing the total door access is preferable. Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email of Office Phone (217) 333-1534 Iow \$ 4,500.00 \$ 3,600.0	Image: Large state in the state is a state of Parking Deck B-4. Campbell Hall folks are interfere with any parking spaces or with ave cacess to the tower. I have had several employees ask for a rack closer to the back door where they have access to the building with their prox cards. We issued very few keys to the front door, so back or side door access is preferable.Avenue Urbana IL 61801 Phone: 217/244-2625 eweather@uiuc.eduAvenue Urbana IL 61801 Phone: 217/244-2625 eweather@uiuc.edu12ILIR <td>11</td> <td>WILL building</td> <td></td> <td></td> <td></td> <td>low</td> <td>\$ 10,000.00</td> <td>\$ 8,000.0</td>	11	WILL building				low	\$ 10,000.00	\$ 8,000.0
12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks across to be to key and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy an expensive rack, but we'd have to pour some concrete to set it on. Iow \$ 4,500.00 \$ 3,600.0	12ILIRold style rack, and there is parking across the streetImmediate interfere with any parking spaces or with access to the tower. I have had several employees ask for a rack closer to the back door where they have access to the building with their prox cards. We issued very few keys to the front door, so back or side door access is preferable.Urbana IL 61801 Phone: 217/244-2625 eweather@uiuc.eduImmediate Phone: 217/244-2625 eweather@uiuc.edu12ILIRold style rack, and there is parking across the streetImmediate m geting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm euddoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.Nell Madigan Email nellm@illinois.edu NetidIow\$ 4,500.00\$ 3,600								
12 ILIR old style rack, and there is parking across the street access to the tower. Nell Madigan Email across the street Iow \$ 4,500.00 \$ 3,600.00 12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new prive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm Iow \$ 4,500.00 \$ 3,600.00	12 ILIR old style rack, and there is parking across the street access to the tower. Phone: 217/244-2625 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy an ewr nellm enlime enlime to building, but we have to buy an expensive rack, but we'd have to buy an expensive rack, but we'd have to pour some concrete Nell Madigan Email nellm@illinois.edu 12 istreet old style rack, and there is parking across the bike falls over. One professor wants us to buy an expensive rack, but we'd have to pour some concrete Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600								
Image: Index i	12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a nexpensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm@illinois.edu Netid Iow \$ 4,500.00 \$ 3,600								
12ILIRold style rack, and there is parking across the streetI'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike failsNell Madigan Email nellm@illinois.edu Netid Office Phone (217) 333-1534Iow s\$ 4,500.00 s\$ 3,600.0 s	12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm@illinois.edu Netl Iow \$ 4,500.00 \$ 3,600			welcome to park their bikes there.					
12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new every little office Phone (217) 333-1534 Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new every little outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm Iow \$ 4,500.00 \$ 3,600.0	12 ILIR old style rack, and there is parking across the lim getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy an ewn nellm rack for our boulding, but we have very little Office Phone (217) 333-1534 Iow \$ 4,500.00 \$ 3,600 ILIR old style rack, and there is parking across the lim getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy an ewn nellm rack for our boulding, but we have very little Office Phone (217) 333-1534 Iow \$ 4,500.00 \$ 4,500.00 \$ 4,500.00					eweather@uluc.eau			
12 ILIR old style rack, and there is parking across the street image: cards. We issued very few keys to the front door, so back or side door access is preferable. Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new very little outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm@illinois.edu Nell Madigan	12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm rack for our building, but we have top pur some concrete to set it on. Nell Madigan Email nellm@illinois.edu Netid Iow \$ 4,500.00 \$ 3,600								
12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600.0 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu Netid Netid 00 ver. One professor wants us to buy a new nellm Office Phone 0/// 333-1534 Iow \$ 4,500.00 \$ 4,500.00 \$ 4,500.00 01 would we have to buy an expensive rack, but we'd have to pour some concrete to set it on. only would we have to pour some concrete Iow	12 ILIR old style rack, and there is parking across the street I'm getting complaints about the racks across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new rack for our building, but we have very little outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600								
Image: street preferable. preferable. preferable. 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike fails out over. One professor wants us to buy a new nack for our building, but we have very little outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on. Nell Madigan Email	ILR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu Iow \$ 4,500.00 \$ 3,600 12 ILIR old style rack, and there is parking across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new nellm Nell Madigan Email nellm@illinois.edu Nell Madigan Email nellm@								
street across the street being the "potato chip" type that damages wheels if the bike falls over. One professor wants us to buy a new very little Office Phone outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	street across the street being the "potato chip" nellm@illinois.edu type that damages wheels if the bike falls Netid over. One professor wants us to buy a new nellm rack for our building, but we have very little Office Phone outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.								
type that damages wheels if the bike falls over. One professor wants us to buy a new nellm rack for our building, but we have very little Office Phone outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	type that damages wheels if the bike falls over. One professor wants us to buy a new nellm rack for our building, but we have very little outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	12	ILIR	old style rack, and there is parking across the	I'm getting complaints about the racks	Nell Madigan Email	low	\$ 4,500.00	\$ 3,600.0
over. One professor wants us to buy a new nellm rack for our building, but we have very little Office Phone outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	over. One professor wants us to buy a new nellm rack for our building, but we have very little Office Phone outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.			street	across the street being the "potato chip"	nellm@illinois.edu			
rack for our building, but we have very little Office Phone outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	rack for our building, but we have very little Office Phone outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.								
outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.				over. One professor wants us to buy a new	nellm			
outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	outdoor space and I'm confident that not only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.								
only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.	only would we have to buy an expensive rack, but we'd have to pour some concrete to set it on.								
to set it on.	to set it on.								
	LOW \$ 16,000.00 \$ 12,800				to set it on.				
	LOW \$ 16,000.00 \$ 12,800					1			

Hi Morgan,

Please clarify the following regarding your letter of inquiry:-1) What is the capacity of each proposed rack?

Each location listed in the requests will have to be examined for capacity. The goal will be to maximize the capacity at each location, based on available space and a cursory review of the needs at that location. The locations estimated as \$1500 are for 5-10 loops, or 10-20 spaces. The locations estimated as \$4500 or \$10,000 are highly dependent on the space available. At the Undergrad, we will get 24 loops, or 48 spaces, for about \$10000. At Freer, we will get 21 loops, or 42 spaces, for about \$4500.

Could you provide a picture of the proposed design?

Please see attached layout standard and rack details. We will use the spacing information from the standard layout, but we are unlikely to add bushes with the bike rack installations.

2) What metric(s) was used to sort projects into high, medium and low priority?

The higher priority locations are bike rack areas that have additional needs, as follows. The Illini Union bike rack is in disrepair AND is causing flooding into the building. Chem Life Science Lab was an agreement with the City of Urbana, where they already paid for and installed the concrete, and we promised to find a way to add the loops. Krannert Art Museum (KAM) is higher because there is already a design laid out (also attached), and because a student brought it to our attention rather than an employee. The Music Annex was brought to my attention by the Campus Lighting Committee last year, and the facilities staff in that building is actively requiring bicyclists to use the appropriate bike parking areas.

The lower priority locations are those that are a matter of convenience rather than necessity. There are additional bike parking facilities near these locations, but across a street.

Everything else was left as medium priority.

3) Would you be willing to discuss locations not on your list with the SSC?

Absolutely! I would like this to be a dialog, and I am eager to get the input of SSC for prioritization.

4) Can you comment on any progress regarding finding a more comprehensive solution to the bike parking issue on campus?

The draft bike plan for campus addresses bike network design, and other bicycle support needs. We have recently established a bike plan steering committee through the regional MPO, CUUATS (<u>http://www.ccrpc.org/planning/transportation/transportation.php</u>). That will serve as the community transportation professionals input avenue. On campus, we will now begin establishing a Campus Bicycle Taskforce, which will assist with the data collection, public engagement, discussion of alternatives, actual writing of the Campus Bike Plan, and implementation of said plan. Once completed, the bike plan will be incorporated into the Campus Master Plan, and funding can be sought for the various implementation steps that will be needed.

In addition to the network aspect of the bike plan, there is a discussion of support needs, such as adequate bike parking throughout campus, and a feasible method for ensuring cyclists use the bike parking facilities instead of trees, railings, and anything that is nailed down. Due to the limited resources of the F&S Parking Department staff for bicycle parking enforcement, I've been working with University Legal Counsel about alternatives for the enforcement. We intend to identify and train departmental affiliates to assist with the enforcement of the bike parking

requirements, per the University Bicycle Code. The control of bike parking was highly sought by our previous Provost, Linda Katehi. The ONLY appropriate means of ensuring correct use of bike parking facilities is by provision of those bike parking areas in convenient, safe, and usable facilities. We have completed the inventory of existing bike parking areas in the University District, and that shows that about half of the current bike parking areas are of poor design. We also have had some progress in getting individual departments to fund their own new bike parking areas, without assistance from SSC. However, the ultimate solution for bike parking needs will be a result of the deliberations of the Campus Bicycle Taskforce which is yet to be started.