

## **Pictures start on next page**

### **Campus Bike Center (right outside)**

- Tools: complete and in good condition
- Pump: broken and detached. A working floor pump, not part of the repair station, has been locked to the station's broken pump as a temporary fix.

### **Altgeld Hall (South side – close to the Eco-Counter)**

- Tools: complete and in good condition
- Pump: broken but intact. Tube does not inflate, possible problem with seal/locking mechanism.

### **Information Sciences building (intersection of Fifth and Daniel St)**

- Tools: complete and in good condition
- Pump: functioning

### **Siebel Center for Design (North side) – on the shared use path by Huff Hall and Wymer Hall**

- Tools: Allen wrench set is broken with two keys detached from the tool itself and placed on top of repair station. Otherwise in okay condition.
- Pump: functioning for Presta valves but not for Schrader

### **Main Library – South side**

- Tools: complete and in good condition
- Pump: functioning

### **Smith Hall – West Side – (East of Foellinger Hall)**

- Tools: complete and in good condition
- Pump: functioning

### **Grainger Library – West side – between Grainger and CIF**

- Tools: complete and in good condition
- Pump: broken and detached, pump handle missing

### **ECE building – South side bike racks – bike racks between ECE and Micro-Nano**

- Tools: missing Allen wrench set and flathead screwdriver
- Pump: broken but intact. Pressure gauge is inaccurate and potential problem with seal

### **Loomis Lab – South side – along Green St – close to the Eco-Counter**

- Tools: missing Allen wrench set and flathead screwdriver.
- Pump: broken and detached



Campus Bike Center



Altgeld Hall



Information Sciences



Siebel Center for Design



Main Library



Smith Hall



Grainger Library



ECE



Loomis Lab